BRADLEY PARISH COUNCIL Risk assessment Report 2025

AMENITIES AREA

One side of the weir bridge under the canal is blocked.
Wall at the entrance of the canalside car park has been knocked down

Action: Repair wall quote received. Report blockage to Canal & River Trust

CEMETERY & SWEET CROFT

Gravestones need checking for movement, 1 in particular (Mawson) has no support on one side. Strimming between old graves required

Action: Sexton asked to check the above grave and do gravestone report on all.

Ask Frank to strim the older graves.

PUBLIC TOILETS

Facia board has rotted, roof is covered in moss but sound.

Action:

SPORTS PAVILION

A new vinyl floor has been laid in the kitchen area.

Changing rooms need cleaning. - Were cleaned before Embsay football commenced.

PLAYING FIELD

Noticeboard needs cleaning and the back board is warped. Cleaned Perspex.

Vegetation in the beck needs clearing from willow tree to the gate.

Artisan well is blocked and overflowing.—Richard has unblocked the drain again.

Litter bin by the car park is rusted and should be replaced.

Action: Report bin to NYC see quote for new bin!

VILLAGE HALL CAR PARK

Pot holes

Action:

PLAY GROUND

As ROSPA report

Rockers are loose and rusting

Bench has fungi growing on the seat

Weeds around the perimeter need to be cleared.

Some welding to be done on climber

Action: Ask Frank to clear weeds—clearance requested.